


# In-Production Photo Report for Windsor Heights Fire Department, IA

Job# 40212

Status as of January 10, 2025

In this report your cab continued through paint while the pump house began initial assembly. In the next report your cab may continue the paint process while the pump house may continue initial assembly.





DSC00033



DSC00034



DSC00035



DSC03123



DSC03124



DSC03125



DSC03126



<https://reliantfire.com/>



An Oshkosh Corporation Company