


In-Production Photo Report for Windsor Heights Fire Department, IA Job# 40212

Status as of January 24, 2025

In this report your cab continued initial assembly, the frame build began, the pump house completed initial assembly, and the body remained staged. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may remain staged, and the body may begin the paint process.





DSC00038



DSC00039




DSC00040



DSC00041



DSC00042



DSC00043



DSC00044



DSC00045



DSC00046



DSC00047



DSC00139



DSC00140



DSC00141



DSC00142



DSC00143



DSC03092



DSC03093



DSC03094



DSC03095



DSC03096



<https://reliantfire.com/>



An Oshkosh Corporation Company