In-Production Photo Report for

West Union Fire Department, IA


Job# 40269

Status as of February 14, 2025

In this report your cab began the paint process in metal finishing. In the next report your cab should continue through paint.







DSC00780



DSC00782



DSC00781



https://reliantfire.com/





An Oshkosh Corporation Company