

In-Production Photo Report for West Union Fire Department, IA Job# 40269

Status as of February 21, 2025

In this report your cab continued through paint, the pump house began initial assembly, and the body began fabrication. In the next report your cab may continue the paint process, the pump house may continue initial assembly, and the body may continue the fabrication process.






DSC00518



DSC00519



DSC00520



DSC03093




DSC03094



DSC03095




DSC03096



DSC03082



DSC03083



DSC03084



DSC03085



DSC03086



<https://reliantfire.com/>



An Oshkosh Corporation Company