

In-Production Photo Report for Windsor Heights Fire Department, IA Job# 40212

Status as of February 07, 2025

In this report your cab and pump house were installed on the frame followed by the body completing initial assembly then merged with the chassis. In the next report your apparatus may complete initial assembly and begin final assembly.





DSC00625



DSC00626



DSC00627



DSC00628




DSC00629



DSC00630



DSC00631



DSC00632



DSC00633



DSC00634



DSC00635



DSC00636



DSC00637



DSC00638



DSC00639



DSC00640



DSC00641



DSC00642



DSC00643



DSC00644



DSC00645



DSC00646



DSC00647



DSC00648



DSC00649



DSC00650



DSC00651



DSC00652



DSC00653



DSC00654



DSC00655



DSC00656



DSC00657



DSC00658



DSC00659



DSC00660



DSC00661



DSC00662



DSC00663



DSC00664



DSC00665



DSC00666



DSC00667



DSC00668



DSC00669



DSC00670



DSC00671



DSC00672



DSC00673



DSC00674




DSC00675



DSC00676



DSC00677



DSC03926



DSC03927



DSC03928



DSC03929



DSC03930



DSC03931



DSC03932



DSC03933



<https://reliantfire.com/>



An Oshkosh Corporation Company