

# In-Production Photo Report for West Union Fire Department, IA Job# 40269

---

Status as of February 28, 2025

In this report your cab completed paint and began initial assembly, the frame build began, the pump house was unavailable for photos, and the body continued the fabrication process. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may be available, and the body may complete fabrication.







DSC01321



DSC01322



DSC01323



DSC01324





DSC01325



DSC00250




DSC00251



DSC00252






DSC00253



DSC00254



DSC00255



DSC03103





DSC03104



DSC03105



DSC03106



<https://reliantfire.com/>



An Oshkosh Corporation Company