

In-Production Photo Report for West Union Fire Department, IA Job# 40269

Status as of March 07, 2025

In this report your cab continued initial assembly, the frame build continued, the pump house continued initial assembly, and the body completed fabrication and began the paint process. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may be painted, and the body may continue through paint.





DSC00220



DSC00221



DSC00222



DSC00223



DSC00224



DSC00282




DSC00283



DSC00284



DSC00285




DSC00286



DSC00287



DSC00288



DSC03066



DSC03067



DSC03068



DSC03069



DSC03070



DSC00946



DSC00947



DSC00948



DSC00949



DSC00950



<https://reliantfire.com/>



An Oshkosh Corporation Company