In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 39501 Status as of May 23, 2025

In this report your cab continued the paint process, the pump house began initial assembly, and the body began fabrication. In the next report your cab may continue through paint, the pump house may continue initial assembly, and the body may complete the fabrication process.
















DSC00468





DSC00469

















FIG

DSC03126





DSC03154



DSC03152







https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company