


In-Production Photo Report for North Shore Fire Rescue, WI Job# 39484

Status as of May 23, 2025

In this report your cab completed the paint process, the pump house remained staged to continue initial assembly, and the body began the paint process in metal finishing. In the next report your cab may begin initial assembly, the pump house may be painted, and the body may continue through paint.






DSC00030



DSC00031



DSC00032



DSC03071



DSC03072




DSC03073



DSC03074




DSC03075



DSC00473



DSC00474



DSC00475



DSC00476



DSC00477



<https://reliantfire.com/>



An Oshkosh Corporation Company