
In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 39501 Status as of May 30, 2025

> In this report your cab completed paint, the pump house continued initial assembly, and the body continued the fabrication process. In the next report your cab may remain staged to begin initial assembly, the pump house may be painted, and the body may complete fabrication.












DSC00949







DSC03187





DSC03189



DSC03358



DSC03355











https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company