


In-Production Photo Report for City of Cedar Rapids Fire Department, IA Job# 39501

Status as of June 06, 2025

In this report your cab began initial assembly, the pump house was painted then continued initial assembly, and the body completed fabrication and began the paint process. In the next report your cab may continue initial assembly, the pump house may complete initial assembly, and the body may continue through paint.





DSC00080



DSC00081



DSC00082



DSC00083



DSC00084



DSC03290



DSC03291




DSC03292




DSC03293



DSC03294



DSC01129



DSC01130



DSC01131



DSC01132



DSC01133



<https://reliantfire.com/>



An Oshkosh Corporation Company