In-Production Photo Report for Clinton Township Fire Department, MI Job# 39726-01 Status as of June 27, 2025

In this report your cab began the paint process, the pump house began initial assembly, and the body began fabrication. In the next report your cab may continue through paint, the pump house may continue initial assembly, and the body may complete fabrication and be staged to begin the paint process.

Due to the annual Pierce facility 4th of July shut down, your next scheduled report will be week ending July 12th, 2025. Thank you. Have a very safe & happy Independence Day week!





Faceboo

301289 (Unit #1) 301390 (Unit #2)

> Job # **39726-01** Bottom: #90 Red Bottom: #90 Red Bottom: #90 Red

ecial Trim on Paint Break:

hrome Molding np/Vel/Enf/Dash CF: N/A

hassis Frame Color: #101 Black uel Tank Color: Line-X (See Special Coatings) ues Rust Proof: N/A

DSC00430




DSC00431



DSC00432



DSC03234







DSC03232






DSC03253





DSC03251









https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company