
In-Production Photo Report for Comstock Fire & Rescue, MI Job# 43560 : PWO#3789181 Status as of June 20, 2025

> In this report your cab was fabricated, the pump house continued initial assembly, and the body completed fabrication and began the paint process. In the next report your cab may be staged to begin the paint process, the pump house may continue initial assembly, and the body may continue through paint.












DSC05266









DSC05269









DSC05171



<image>

DSC05172





DSC05251



DSC05250







https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company