

In-Production Photo Report for Marathon Petroleum Company, MI Job# 38534


Status as of February 21, 2025

In this report your chassis remained staged to continue assembly (no photos), the pump house continued initial assembly, and the body completed initial assembly. In the next report the chassis may remain staged, the pump house may be painted, and the body may remain staged.



For valued customers of





DSC03027



DSC03028



DSC03029



DSC03030



DSC03031



DSC00562



DSC00563



DSC00564