## **In-Production Photo Report for**

North Shore Fire Rescue, WI Job# 39484

Status as of May 30, 2025

In this report your cab began initial assembly, the frame build began, the pump completed initial assembly, and the body continued through paint. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may remain staged, and the body may complete the paint process.







DSC00140





DSC00141



DSC00142 DSC00143



DSC00144



DSC00157



DSC00156



DSC00158



DSC00159





DSC00160




DSC00258 DSC00259



DSC00260



DSC00262



DSC00261



DSC00263



DSC00726



DSC00728



DSC00727



DSC00729



DSC00730



https://reliantfire.com/





**An Oshkosh Corporation Company**