

In-Production Photo Report for City of Sterling Heights Fire Department, MI Job# 39160


Status as of May 09, 2025

In this report your cab completed paint, the frame build continued, and the body was fabricated and began the paint process. In the next report your cab may begin initial assembly, the frame build may continue, and the body may continue through paint.



For valued customers of





DSC00853



DSC00854



DSC00855



DSC00187



DSC00188



DSC00189



DSC00190




DSC00191



DSC00192



DSC00193



DSC00792



DSC00793



DSC00794