

In-Production Photo Report for City of Sterling Heights Fire Department, MI Job# 39160

Status as of May 16, 2025

In this report your cab was staged to begin initial assembly, the frame build continued, and the body completed the paint process. In the next report your cab may begin initial assembly, the frame build may continue, and the body may remain staged to begin initial assembly.



For valued customers of



Item	
39160 BLACK CAB INTERIOR & FLOOR	Description

DSC00045



DSC00046



DSC00047



DSC00048



DSC00049



DSC00148



DSC00149



DSC00150



DSC00151



DSC00152



DSC03618



DSC03619



DSC03620



DSC03621



DSC03622