

In-Production Photo Report for City of Sterling Heights Fire Department, MI Job# 39160

Status as of May 23, 2025

In this report your cab completed initial assembly and was merged with the frame while the body began initial assembly. In the next report the body may complete initial assembly and be installed on the chassis at the start of initial apparatus assembly.



For valued customers of





DSC03576



DSC03577



DSC03578



DSC03579



DSC03580



DSC03519



DSC03520



DSC03521



DSC03522



DSC03523