**In-Production Photo Report for** Clinton Township Fire Department, MI Job# 39726-01 Status as of July 18, 2025

> In this report your cab began initial assembly, the pump house completed initial assembly and was staged, and the body continued through paint. In the next report your cab may continue initial assembly, the pump house may remain staged, and the body may complete the paint process and begin initial assembly.





## DSC00019







DSC00017



<image><section-header>



DSC00129



DSC00131

## DSC00134



DSC00132









DSC03661



DSC03662







https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company