In-Production Photo Report for Clinton Township Fire Department, MI Job# 39726-02 Status as of July 18, 2025


> In this report your cab completed paint, the pump house continued initial assembly, and the body remained staged to begin the paint process. In the next report your cab may remain staged to begin initial assembly, the pump house may be painted then continue initial assembly, and the body may begin in paint.





DSC00006





DSC00004






DSC00005

DSC03145

DSC00647







DSC03146





DSC03147

DSC00651







DSC00650



https://reliantfire.com/

Find us on Facebook



An Oshkosh Corporation Company