


In-Production Photo Report for City of Iowa City Fire Department, IA Job# 43837

Status as of July 11, 2025

In this report your cab and pump house completed initial assembly then were merged with the frame, the pedestal arrived and was staged, and the body was fabricated then completed the paint process. In the next report your chassis may be staged to continue assembly while the pedestal and body may begin initial assembly.





DSC03000



DSC03001



DSC03002



DSC03003



DSC03004



DSC03005



DSC03006



DSC03007



DSC03008



DSC03009



DSC03010



DSC03011



DSC03012



DSC03013



DSC03014



DSC03015



DSC03016



DSC03017



DSC03018



DSC03019



DSC03020



DSC03021



DSC03022



DSC03023



DSC03024



DSC03025



DSC03026



DSC03027



DSC03028



DSC03029



DSC03030



DSC03031



DSC03032



DSC03033



DSC03034



DSC03035



DSC03036



DSC03037



DSC03038



DSC03039



DSC03040



DSC03041



DSC03042



DSC03043



DSC03044



DSC03045



DSC03046



DSC03047



DSC03048



DSC03049



DSC03050



DSC03051



DSC03052



DSC03053



DSC03054



DSC03055



DSC03056



DSC03057



DSC03058



DSC03059



DSC03060



DSC03061



DSC03062



DSC03063



DSC03064




DSC03065



DSC03066



DSC03067



DSC03068



DSC03069



DSC03070



DSC00571



DSC00572



DSC00573



DSC00574



DSC00575



<https://reliantfire.com/>



An Oshkosh Corporation Company