

In-Production Photo Report for Gaines Charter Township, MI Job# 39765

Status as of August 22, 2025

In this report your cab began in paint while the pump house structure was fabricated then painted. In the next report your cab may continue through paint while the pump house may begin initial assembly.





DSC00478



DSC00479



DSC00480



DSC03237



DSC03238



DSC03239



<https://reliantfire.com/>



An Oshkosh Corporation Company