In-Production Photo Report for


Sault Ste. Marie Fire Department, MI Job# 43629

Status as of August 22, 2025

In this report your cab began the paint process, the pump house began initial assembly, and the body completed fabrication. In the next report your cab may continue through paint, the pump house may continue initial assembly, and the body may be staged to begin the paint process.







DSC00499



DSC00501



DSC00500



DSC03263



DSC03264



DSC03032 DSC03033



DSC03265





DSC03034



DSC03036



DSC03035



https://reliantfire.com/





An Oshkosh Corporation Company