


In-Production Photo Report for Altoona Fire Department, IA Job# 39891

Status as of December 05, 2025

In this report your cab completed fabrication and began the paint process while the pump house structure was fabricated. In the next report your cab may continue through paint while the pump house structure may remain staged.






DSC00623



DSC00624



DSC03086



DSC03087



<https://reliantfire.com/>



An Oshkosh Corporation Company