

# In-Production Photo Report for

Walker Fire Department, IA


Job# 40755 : PWO# 32027542

---

Status as of December 12, 2025

In this report your commercial chassis completed the paint process, the pump house continued initial assembly, and the body completed fabrication and began the paint process. In the next report your chassis may be staged to begin preparations for fire and emergency use, the pump house may be painted then continue initial assembly, and the body may continue through paint.





DSC07014



DSC07015



DSC07016



DSC07017



DSC07018




DSC07019



DSC07020



DSC07021



DSC07286



DSC07287




DSC07288



DSC07289



DSC07290



DSC07489



DSC07490



DSC07491



DSC07492



DSC07493



<https://reliantfire.com/>



An Oshkosh Corporation Company