

In-Production Photo Report for


Altoona Fire Department, IA

Job# 39891

Status as of January 09, 2026

In this report your cab completed paint and began initial assembly, the frame build continued, the pump house was painted then continued initial assembly, and the body completed fabrication and the paint process. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may complete initial assembly, and the body may be staged to begin initial assembly.





DSC00569



DSC00570



DSC00571



DSC00572



DSC00573



DSC00096



DSC00097



DSC00098



DSC03060




DSC03061



DSC03062



DSC03063



DSC00405



DSC00406



DSC00407



DSC00408



DSC00409



<https://reliantfire.com/>



An Oshkosh Corporation Company