




Photo Album for McFarland Fire and Rescue, WI Job 36382 April 22, 2022

In this report the torque box was installed on the chassis, the rear body continued initial assembly, and the aerial device sections remain staged with no photos. In your next report the body may be installed on the chassis, and the aerial device may be staged with no photos until assembly begins.



DSC00266



DSC00267



DSC00268



DSC00269



DSC00270



DSC00271



DSC00272



DSC00273



DSC00274



DSC00275



DSC00276



DSC00277



DSC00278



DSC00279



DSC00280



DSC00281



DSC00282



DSC00283



DSC00284



DSC00285



DSC00286



DSC00287



DSC00288



DSC00289



DSC00290



DSC00291



DSC00292



DSC00293



DSC00294



DSC00295



DSC00296



DSC00297



DSC00298



DSC00299



DSC00300



DSC00301



DSC00302



DSC00303



DSC00304



DSC00305



DSC00306



DSC00307



DSC00308




DSC00309



DSC00310



DSC00311



DSC01090



DSC01091



DSC01092



DSC01093



DSC01094



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

