

In-Production Photo Report for Monroe Fire Department, WI Job# 39009


Status as of June 28, 2024

In this report the torque box was installed on the chassis while the front and rear body modules completed initial assembly. In the next report the rear body module may be merged with the chassis in the start of initial assembly while the front body module may remain staged.

**Due to the annual Pierce facility summer shut down,
your next scheduled report is July 12, 2024.**

Thank you. Have a very safe & happy Independence Day week!





DSC00203



DSC00204



DSC00205



DSC00206




DSC00207



DSC00208



DSC00209



DSC00210



DSC00211




DSC00212



DSC00213



DSC00214



DSC00215



DSC00216



DSC00217




DSC00218



DSC00219



DSC03539



DSC03540



DSC03541



DSC01059



DSC01060



DSC01061



DSC01062



DSC01063



<https://reliantfire.com/>



An Oshkosh Corporation Company