


Photo Album for Palo Benefited FD 6, IA

Job # 30857

W/O # 21855577

September 8, 2017

This week the chassis continued with chassis prep. The pump house finished the paint process and began final pump assembly. The body remained in staging (no photos). Next week the chassis should continue with chassis prep. The pump house could be mounted on the chassis and the body could start receiving trim and wiring harnesses.




DSC06882



DSC06883



DSC06884



DSC06885



DSC06886



DSC06887



DSC06888



DSC06889



DSC06890



DSC06891



DSC06892



DSC06893



DSC06894



DSC06895



DSC06896



DSC06897



DSC07104



DSC07105




DSC07106



DSC07107



DSC07108



DSC07109



DSC07110



DSC07111



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2017 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956