The background of the slide features a composite image. On the left, a firefighter in full gear, including a helmet and jacket, is shown from the chest up, holding a hose. On the right, a red fire truck is visible with the words "FIRE-RESCUE" printed on its side. The overall image is semi-transparent, allowing the text to be clearly legible.

Photo Album for Slinger Fire Department, WI Job 30985 September 1, 2017

Earlier this week alignment and initial testing were completed. At the time of this report your apparatus was moving down the post-test assembly line; where remaining content is added and/or additional assembly work is completed. Next week your apparatus should finish the post-test line and may be released for 3rd party testing.

PI
 ITEM NO. 30985
 TRUCK NO. 22037602
 INTERNAL ORDER NO. 22037729
 AERIAL NO. _____
 TORQUE BOX NO. _____
 V.I.N. NO. 018306
 CHASSIS BY: PIERCE CUSTOMER
 DEALER: Reliant Fire Apparatus Inc.
 CUSTOMER: Slinger FD
 STATE: WI
 C/M: Resch
 PAINT NO: #40 & #10

DSC08000



DSC08001



DSC08002



DSC08003



DSC08004



DSC08005



DSC08006



DSC08007



DSC08008



DSC08009



DSC08010



DSC08011



DSC08012



DSC08013



DSC08014



DSC08015



DSC08016



DSC08017



DSC08018



DSC08019



DSC08020



DSC08021



DSC08022



DSC08025



DSC08026



DSC08027




DSC08028



DSC08029



DSC08030



DSC08031



DSC08032



DSC08033



DSC08034




DSC08035



DSC08036



DSC08037



DSC08038



DSC08039




DSC08040



DSC08041



DSC08042




DSC08043



DSC08044



DSC08045



DSC08046



DSC08047



DSC08048



DSC08049



DSC08050



DSC08051



DSC08052



DSC08053



DSC08054



DSC08055



DSC08056



DSC08057



DSC08058



DSC08059



DSC08060



DSC08061



DSC08062



DSC08063



DSC08064



DSC08065



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2017 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956