



Photo Album for Dane Vienna Joint Fire District, WI Job 33006 May 10, 2019

This week your cab began the content installation process, your chassis arrived and was assembled, your pump was installed in your pumphouse, and your body began the paint process. Next week your cab may finish content installation, your chassis may have powertrain components installed, your pumphouse may begin the paint process, and your body may complete the paint process.



DSC08300



DSC08301



DSC08303



DSC08304



DSC08305



DSC02980



DSC02981



DSC02982



DSC02983



DSC02984



DSC00145



DSC00146



DSC00147



DSC00148



DSC00149

Body

Work Order # 24261485

Job # 33006 Process Start Date: 5-11

- All work is to be completed following work instructions in PSD Manual
- Metal Finishing work must meet "Acceptance Criteria"
 - Attach Activity List packet to D.S. Front Compartment

Clock # Start	Clock # Finish	Clock # N/A	Activity
	394		Body Strip Operation
			Inspected that the body is properly mounted
			Walkway in tank area is proper for the body
			Strip D.S. Body
			Strip P.S. Body
			Strip Tank Area
			Complete form QSD 0589 "Second Generation"
			Attach copy of QSD 0300 "Paint Shop"

DSC07023



DSC07024



DSC07025



DSC07026



DSC07027



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

© 2005-2019 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956