



Photo Album for Menomonee Falls Fire Department, WI Job 34847 June 26, 2020

This week your cab remained in queue to begin the paint process while your PUC module completed the paint process. In your next report, you may see that your cab may have started the paint process and your PUC module may begin to have the PUC manifold installed.

Due to the annual Pierce plant summer shut down, your next scheduled report will be week ending July 11, 2020.

Thank you - Have a very safe, healthy, & happy Independence Day week!



DSC01940



DSC01941




DSC01942



DSC01943



DSC01944



DSC01890



DSC01891



DSC01892



DSC01893



DSC01894



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

