


Photo Album for Onalaska Fire Department, WI Job 35342 January 08, 2021

In this report your cab completed paint while the PUC module is having plumbing installed and the body fabrication began. In your next report your cab may begin assembly while the PUC module is staged and body fabrication continues.



DSC04189



DSC04190



DSC04191



DSC07465



DSC07466



DSC07467



DSC07468



DSC07469



DSC00070



DSC00071



DSC00072



DSC00073



DSC00074



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956