


Photo Album for Western Lakes Fire District, WI Job 35045 January 08, 2021

In this report your cab is offsite having protective coatings applied while the chassis frame build started ,and the body completed fabrication with a start in paint. In your next report the cab may return while the frame build continues and the body continues in paint.



DSC08407



DSC08408




DSC08409



DSC08410



DSC08411



DSC07475



DSC07476



DSC07477



DSC07478



DSC07479



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956