



# Photo Album for Fitchburg Fire Department, WI Job 35149 February 05, 2021

In this report, your chassis assembly remains staged while the body continued refurbishment. In the next report the chassis may remain staged with the body may make progress with refurbishment.


Your next scheduled report from Weyauwega is the week ending February 20, 2021



DSC09002



DSC09016



DSC09017



DSC09018



DSC09019



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2020 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956