
Photo Album for Mount Horeb Fire Department, WI Job 35094 February 19, 2021

In this report your cab has completed assembly while the frame build continued, the pump house has completed paint, and the body made progress in paint. In your next report the cab may be merged with the chassis followed by the pump house while the body completes paint and starts initial assembly.



DSC06676



DSC06678



DSC06677



DSC06679





DSC06680



DSC07270



DSC06681



DSC07271





DSC07272



DSC07274

Find us on Facebook



DSC07273



DSC07275



DSC07276



DSC09320



DSC07277



DSC09321




DSC09322



DSC09324



DSC09323



DSC07594





DSC07595



DSC07597



DSC07596





http://reliantfire.com/



An Oshkosh Corporation Company

