


# Photo Album for Onalaska Fire Department, WI Job 35342 February 12, 2021


In this report your apparatus started final assembly while the aerial device sections have arrived. In your next report your apparatus may continue final assembly while the aerial device could begin assembly.



DSC01758



DSC01759



DSC01760




DSC01761



DSC01762



DSC01763




DSC01764



DSC01765



DSC01766



DSC01767



DSC01768



DSC01769



DSC01770



DSC01771



DSC01772



DSC01773



DSC01774



DSC01775



DSC01776



DSC01777




DSC01778




DSC01779



DSC01780



DSC01781




DSC01782



DSC01783



DSC01784



DSC01785





DSC01786



DSC01787



DSC01788



DSC01789



DSC01790



DSC01791



DSC01792



DSC01793



DSC01794



DSC01795



DSC01796



DSC01797



DSC01798



DSC01799



DSC01800



DSC01801



DSC01802



DSC01803



DSC01804



DSC01805



DSC01806




DSC01807



DSC01808



DSC01809



DSC09112



DSC09113



DSC09114



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956