


# Photo Album for Tess Corners Volunteer Fire Dept., WI Job 35030 February 19, 2021


In this report the apparatus continued final assembly while the aerial device completed assembly. In your next report final assembly may continue on the apparatus and the aerial device may be staged.



DSC01972



DSC01973



DSC01974



DSC01975



DSC01976



DSC01977



DSC01978



DSC01979



DSC01980



DSC01981



DSC01982



DSC01983



DSC01984



DSC01985



DSC01986



DSC01987



DSC01988



DSC01989



DSC01990



DSC01991



DSC01992



DSC01993



DSC01994



DSC01995



DSC01996



DSC01997



DSC01998



DSC01999





DSC02000



DSC02001



DSC02002




DSC02003



DSC02004



DSC02005



DSC02006



DSC02007



DSC02008



DSC02009



DSC02010



DSC02011



DSC02012



DSC02013



DSC02014



DSC02015



DSC02016



DSC02017



DSC02018



DSC02019



DSC02020



DSC02021



DSC02022



DSC02023



DSC02024




DSC02025



DSC02026



DSC02027



DSC09191



DSC09192



DSC09193



DSC09194





DSC09195



DSC09196



DSC09197



DSC09198



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956