


# Photo Album for Belleville, WI Job 35255 February 26, 2021

In this report your cab made progress in paint while the pump house assembly has started, and body fabrication continued. In your next report the cab may complete the paint process while the pump house may be painted, and the body begins the paint process.



DSC06904



DSC06905



DSC06906



DSC06907



DSC06908



DSC09164



DSC09165




DSC09166



DSC09167



DSC09168



DSC09089



DSC09090



DSC09091



DSC09092



DSC09093



<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956