

Photo Album for Belleville, WI Job 35255 March 05, 2021


In this report your cab started assembly while the frame has started assembly, the pump house is in paint, and the body has made progress in paint. In your next report the cab may be merged with the chassis while the pump house completes paint, and the body makes progress in paint.



DSC07612



DSC07613



DSC07614



DSC07615



DSC07616



DSC07302



DSC07303



DSC07304



DSC07305



DSC07306




DSC07307



DSC07308



DSC07309



DSC09185



DSC09186



DSC07029



DSC07030



DSC07031



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956