

Photo Album for Fox Lake Community Fire Association, WI Job 35481 March 05, 2021

In this report your cab completed paint while the frame build started, and the body started paint. In your next report your cab may begin assembly while the frame build may continue, and the body may make progress in paint.



DSC07109



DSC07110



DSC07111



DSC07112



DSC07113



DSC08328



DSC08329




DSC08330



DSC08331



DSC08333



DSC08334



DSC08335



DSC08336



DSC06973



DSC06974



DSC06975



DSC06976



DSC06977



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956