
Photo Album for West Bend Fire Department, WI Job 35391 April 16, 2021

In this report your cab started assembly, the frame build began, the front body module is having the manifold installed, the torque box is staged, and the body is released to paint. In your next report your cab and frame build assembly may continue while the forward body module is staged, the torque box is staged, and the body makes progress in paint.



DSC05002



DSC05004



DSC05003



DSC05005






DSC05006



DSC04662



DSC04661



DSC04663





DSC04664



DSC05220



DSC04665



DSC05221





DSC05222



DSC05224



DSC05223



DSC00373



DSC00374



DSC04773



DSC04772



DSC04774









DSC04776





http://reliantfire.com/



An Oshkosh Corporation Company

