Photo Album for Fennimore Fire Dept., WI Job # 35950 W/O # 27293370 June 26, 2021

This week the cab began the paint process, and the pump house structure was in staging (no photos). The fire pump was in staging (no photos), and the body continued with fabrication. Next week the cab should finish the paint process and the

chassis frame may arrive. The pump house structure should be in staging and the fire pump should begin to receive valves and plumbing. The body should finish with fabrication.



DSC00111



DSC00113



DSC00112



DSC00114









DSC00116





http://reliantfire.com/



An Oshkosh Corporation Company



