


# Photo Album for Wauwatosa Fire Department, WI Job 35764-01 June 25, 2021

In this report your cab started assembly while the frame continued assembly, the pump house was assembled, and the body completed paint. In your next report your cab may continue assembly while the frame, and pump house are staged, and the body begins initial assembly.

**Due to the Pierce 4<sup>th</sup> of July plant shut down, your next scheduled report is July 9, 2021.**  
Thank you & have a very safe and happy Independence Day week!



DSC04477



DSC04478



DSC04479



DSC04480




DSC04481



DSC04535



DSC04536



DSC04537




DSC04538



DSC04539



DSC04540



DSC04541



DSC04542



DSC04543



DSC04544



DSC04545



DSC04573



DSC04574




DSC04575



DSC04576



DSC04577



DSC01993



DSC01994



DSC01995



DSC01996



DSC01997





<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

©2005- 2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956