


Photo Album for Wauwatosa Fire Department, WI Job 35764-02 June 25, 2021

In this report your cab and frame started assembly while the pump house was painted, and the body released to paint. In your next report the cab and frame assembly may continue while the pump house assembly is completed, and the body begins the paint process.

Due to the Pierce 4th of July plant shut down, your next scheduled report is July 9, 2021.

Thank you & have a very safe and happy Independence Day week!




DSC04492



DSC04493




DSC04494



DSC04495



DSC04496



DSC04858



DSC04859



DSC04860



DSC04861



DSC04862



DSC04863



DSC00138



DSC00139




DSC00140



DSC00141



DSC00142



DSC04652



DSC04653



DSC04654



DSC04655



DSC04656



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956