Photo Album for Bettendorf, IA Job # 35571 W/O # 26923649 July 24, 2021

This week the chassis finished the paint process, and the body was unavailable for photos in paint. Next week the chassis should begin preparations for fire service and the body should finish the paint process.



<image>

DSC00305

DSC00304





DSC00307 © 2005-2021 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC00306



http://reliantfire.com/



An Oshkosh Corporation Company



© 2005-2021 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

