

Photo Album for Bettendorf, IA Job # 35571 W/O # 26923649 July 31, 2021

This week the chassis began preparations for fire service, and the body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body should continue to receive trim and wiring harnesses.



DSC00289



DSC00291



DSC00290



DSC00292





DSC00450



DSC00452



DSC00451



DSC00453





http://reliantfire.com/



An Oshkosh Corporation Company



