



# Photo Album for Fennimore Fire Dept., WI

Job # 35950

W/O # 27293370

July 24, 2021

This week the cab finished the paint process, and the pump house structure was in staging (no photos). The fire pump was in staging (no photos), and the body was unavailable for photos in paint. Next week the cab could begin to receive trim and wiring harnesses and the chassis frame should arrive. The pump house structure should be in staging and the fire pump should begin to receive valves and plumbing. The body should finish with paint.



DSC00111



DSC00112



DSC00113



DSC00114





<http://reliantfire.com/>



An Oshkosh Corporation Company



*Your Vision to Quality & Safety*

© 2005-2021 Fire & Safety Consulting, LLC  
Neenah, Wisconsin 54956