




Photo Album for Marshalltown Fire Department, IA Job 35683 July 09, 2021

In this report your cab began assembly while the chassis build continued, and the body completed paint. In your next report the cab may be merged with the chassis while the body starts initial assembly.



DSC04730



DSC04731




DSC04732



DSC04733



DSC04734



DSC01798



DSC01799




DSC01800



DSC01801



DSC01802



DSC04584



DSC04585



DSC04586



DSC04587



DSC04588



<http://reliantfire.com/>



An Oshkosh Corporation Company



Your Vision to Quality & Safety

©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956