Photo Album for Stanwood Fire Dept., IA Job # 35507 W/O # 26831113 July 17, 2021

This week the chassis continued with chassis prep and the pump house was mounted. The body continued to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body should be mounted.



DSC00340



DSC00342



DSC00341



DSC00343





DSC00344



DSC00346



DSC00345



DSC00347





DSC00348



DSC00350



DSC00349



DSC00351





DSC00352



DSC00354



DSC00353



DSC00355






DSC00356



DSC00358



DSC00357



DSC00359









DSC00361





http://reliantfire.com/



**An Oshkosh Corporation Company** 



